

Client:

Clayton Home Inspection  
10 Powdermill Rd.  
Maynard, MA 01754

ReportDate: 11/16/2011

**Certificate of Analysis**

Cook, Debbie, 374 Ashby Rd, Ashburnham MA

Parameter	Method	Result	MCL	MRL	Date of Analysis	Analyst
<b>- Bathroom - Raw</b>						
<i>Sampled: 11/12/2011 10:08:00 AM by T Herbst</i>						
Total Coliform, /100ML	READYCULT COLIFORM	Absent	0/Absent	Absent	11/14/2011 11:30:00 AM	M-MA1118
Calcium, MG/L	EPA 200.7	21.7	Not Spec	1	11/15/2011	M-MA1118
Copper, MG/L	EPA 200.7	ND	1.3	0.01	11/15/2011	M-MA1118
Iron, MG/L	EPA 200.7	0.15	0.3	0.01	11/15/2011	M-MA1118
Magnesium, MG/L	EPA 200.7	6.8	Not Spec	1	11/15/2011	M-MA1118
Manganese, MG/L	EPA 200.7	# 0.099	0.05	0.005	11/15/2011	M-MA1118
Sodium, MG/L	EPA 200.7	18.1	See Note	1	11/15/2011	M-MA1118
Alkalinity, MG/L	SM 2320B	104	Not Spec	1	11/15/2011	M-MA1118
Ammonia, MG/L	SM 4500-NH3-D	ND	Not Spec	0.1	11/15/2011	M-MA1118
Chloride, MG/L	EPA 300.0	1.1	250	1	11/14/2011	M-MA1118
Chlorine, Free Residual, MG/L	SM 4500-CL-G	ND	Not Spec	0.02	11/14/2011	M-MA1118
Color Apparent, CU	SM 2120B	ND	15	1	11/14/2011	M-MA1118
Conductivity, UMHOS/CM	SM 2510B	240	Not Spec	1	11/14/2011	M-MA1118
Hardness, Total, MG/L	SM 2340B	82	Not Spec	2	11/15/2011	M-MA1118
Nitrate as N, MG/L	EPA 300.0	ND	10	0.05	11/14/2011	M-MA1118
Nitrite as N, MG/L	EPA 300.0	ND	1	0.01	11/14/2011	M-MA1118
Odor, TON	SM 2150B	0	3	0	11/14/2011	PN
pH, PH AT 25C	SM 4500-H-B	7.7	6.5 - 8.5	NA	11/14/2011	M-MA1118
Sediment, pos/neg	-----	NEG	-----	NEG	11/14/2011	PN
Sulfate, MG/L	EPA 300.0	17.5	250	1	11/14/2011	M-MA1118
Turbidity, NTU	EPA 180.1	0.9	Not Spec	0.1	11/14/2011	M-MA1118

MCL=Maximum Contaminant Level (EPA Limit), MRL = Minimum Reporting Level  
Sodium Guidelines- Mass 20, EPA 250, # = Result Exceeds Limit or Guideline  
ND = None Detected (<MRL), \* = Background Bacteria Noted